Control the Quadrat Input I/O Tags (Qi) (HI/Monitoring and Controlling of D2000 System Objects)

Controlling quadrat input I/O Tags (QI)

Clicking a graphic object with an I/O Tag of QI type (quadrat input) connected to control (the user has insufficient access rights) opens the same control window as described in the chapter Controlling digital inputs I/O tags (DI).