Logon to the process UPM

!!! WARNING: Process D2000 UPM is substituted by D2000 CNF !!!

Before working with the process D2000 UPM, it is necessary to log on. To work with the process D2000 UPM, the user must have the *administrator* access rights.

The logon dialog box is displayed after starting the process D2000 UPM. If the dialog box is not opened (e.g. after logoff from the process), use the following procedure to log on to the process D2000 UPM:

1. Select **Logon** item from **System** menu.
2. Enter your name and password into the displayed dialog box.

User's logon to the process D2000 UPM is executed after entering the user's name and password. All disabled items in the menus are to be available.

ⓘ **Related pages:**

D2000 UPM