

Proportional displayer

Proportional display expresses the contribution of a value to a total. Total is created by the sum of values of all objects displayed in the diagram. There are 5 display types available:



Examples of a proportional display displayed in the D2000 HI process:




Create pie diagram

- 1. In the Drawing toolbar, click the **Pie diagram**
- 2. Point the mouse cursor to the position of the first diagram corner and click.
- 3. Point the mouse cursor to the position of the diametric diagram corner and click.

The parameters for connecting a pie diagram are being configured in the palette Connect object through the following tabs.

Objects




Object nr. 1 up to Object nr. 12

Each displayer of the *Pie diagram* type can display the values of as many as 12 objects. So the tab **Objects** contains input edit boxes allowing to define 12 objects. To define the objects to display in the displayer either enter its names or select them from a list opened by clicking the button placed right from the input box.

Color for displaying the given object is defined by clicking the button placed left from the input box.

For the object of Structured variable type, you must define the column name (the parameter **Column**) and the row number (the parameter **Row**). For the object of Value array type, you must define an item (the button **L**) whose value will be displayed.


Parameters



Type

	Pie diagram	Each value is represented by a sector whose size corresponds to the total value.
	Horizontal displayers	Each value is represented by a bar whose weight corresponds to the total value.
	Vertical displayer	Each value is represented by a bar whose height corresponds to the total value.
ä	Horizontal percentage displayer	Each value is represented by a percentage placed in the corresponding section of the displayer.
∃×	Vertical percentage displayer	Each value is represented by a percentage placed in the corresponding section of the displayer.

Appearance



Frame and Fill

The parameters **Frame** and **Fill** allow to define colors for the parts (frame and fill) of the proportional display. Color is defined by selecting from the color palette opened by clicking the color sample of the corresponding parameter. The frame can be switched on/off as necessary for the Pie diagram.

Number of decimal places

The number of decimal places for percentages is displayed in the displayer.

Control

The parameters placed on the tab are identical with the parameters on the tab Control of the Connect object palette.

Script

Reference variable

Specifies the name of the displayer in the form of a reference variable for use in the picture script.

Metadata

Assignment of application data (metadata) to a graphic object. If the object contains some metadata, the name of the first record will be displayed in the button. Multiple records are indicated by ",...".

Event

The list box allows a user to select the active picture event for the displayer. The list box contains the following active picture events:

- OnClick
- OnMouseDown
- OnMouseEnter
- OnMouseLeave
- OnUserInput

Event Handler

The button opens the active picture script to define the active picture event specified by the parameter Event.

Info text/URL

Info text

Text to display as a tooltip when the user points the mouse cursor to the displayer in the picture opened in the D2000 HI process. Possibility to use the Dictionary (to open press CTRL+L).

URL

Definition of the URL address to open a web page from a picture. The address may be set also in the picture script by the function %HI_SetOBJURL.

Requirements

Minimum supported version D2000 V12.1N



Related pages:

Displayers
Graphic object manipulation functions