

Process Alarm States (Work with D2000 HI)

Process alarm states

Process alarms can occur in various states. An overview of these states is described in the following table.

Object state	Cause
Normal (NoAlarm)	Condition to raise the process alarm is not met.
Alarm	Condition to raise the process alarm has been met.
Acknowledged	Operator acknowledged the process alarm.
Blocked	The alarm is blocked by operator, or the Silent parameter has been checked at the alarm configuration in process D2000 CNF .
Unacknowledged	Condition to finish the alarm, for an acknowledgement-required status alarm, has been met before it is acknowledged.



Related pages:

[Graphic alarm symbols](#)