

DeleteList

Declaration

```
void (_stdcall *DeleteList)(LinListH List);
```

Parameters

List	Handle to a linked list.
------	--------------------------

Description

The function deletes the linked list. All items, written in the list, must be deleted by using the call-back function [DeleteEI](#) before deleting the list.



Related pages:

[D2000 KomAPI - call-back functions](#)