

HI_SetRectRounding

%HI_SetRectRounding function

Funkcia

Function %HI_SetRectRounding sets the rounding of the corners of rectangles, the text in the rectangle with the background and the edges of windows controls.

Deklarácia

```
%HI_SetRectRounding(  
  INT in _refId,  
  INT in _rounding1,  
  [, INT in _rounding2  
  , INT in _rounding3  
  , INT in _rounding4]  
)
```

Parametre

_refId	Reference to displayer (reference variable). .
_rounding1	rounded corners upper left
_rounding2	optional corner rounding parameter upper right, if not specified _rounding1 is used
_rounding3	optional corner rounding parameter upper down, if not specified _rounding1 is used
_rounding4	optional corner rounding parameter left down, if not specified _rounding1 is used

Poznámka

Parameters _rounding2,_rounding3,_rounding4 all or none must be entered.

Príklad

```
; corner roundings  
%HI_SetRectRounding(_RFID_BOX, 2, 3, 4, 5)  
%HI_SetRectRounding(_RFID_BOX, 0, 0, 0, 0)  
  
; shortened  
%HI_SetRectRounding(_RFID_BOX, 2) ; set all to 2  
%HI_SetRectRounding(_RFID_BOX, 0) ; switch off
```



Related pages:

- [Graphic object manipulation functions](#)
- [Function arguments - types](#)