

# D2000 HI - Human Interface

The process HI (Human Interface) provides communication of D2000 communication and dispatching system with operator. The process allows to display system data via the graphic interface GUI of the operating system Windows. The process HI allows to:

- display values and states of objects (I/O tags and eval tags, stations, lines, alarms) in graphic and numerical forms
- control output objects : digital outputs, analog and integer outputs, stations, time outputs,
- display graphs,
- display graphic reports,
- browse historical values,
- browse logged system data,
- start reports,
- run command files,
- control alarms (acknowledge, block, unblock).

## Note

- To work with the process D2000 HI, see the topic [Operator's work with D2000 HI process](#).
- [Human Interface on separate windows desktop](#) can be run.