

OnLostFocus

OnLostFocus picture event

Declaration	Global handler: <pre>ENTRY OnLostFocus(IN INT _refId) ; script actions END OnLostFocus</pre> Special handler: <pre>ENTRY XXX_OnLostFocus ; script actions END XXX_OnLostFocus</pre>				
Parameters	<table><tr><td>_refId</td><td>Parameter of Int type (required for global handler).</td></tr><tr><td>XXX</td><td>Name of the reference variable assigned to Windows control (without the character "_").</td></tr></table>	_refId	Parameter of Int type (required for global handler).	XXX	Name of the reference variable assigned to Windows control (without the character "_").
_refId	Parameter of Int type (required for global handler).				
XXX	Name of the reference variable assigned to Windows control (without the character "_").				
Description	The event is being generated when the Windows control (specified by its reference variable <i>_refId</i>) loses focus.				
Example	Special picture event handler: <pre>ENTRY List_OnLostFocus ; script actions END List_OnLostFocus</pre> Global picture event handler: <pre>ENTRY OnLostFocus(IN INT _refId) ; _refId - value of local reference variable assigned to Windows control IF _refId = 0 THEN ; no reference variable assigned ELSIF _refId = _editRefId THEN ; script actions ENDIF END OnLostFocus</pre>				
Note	If both handlers are defined in picture script, the global handler will never be called for <i>_refId=_List</i> , because special handler is already defined.				



Related pages:

- [Picture event handler](#)
- [Picture events](#)