

Example (Requirement for value status)

Requirement for status of object value - example

DDE reference:

= D_2000 | STATUS!U.Kx_O2_Ref_Plyn

This DDE reference returns for example the string **N;VH;**

N means that the object value is valid. **VH** indicates the value is higher than VHL (Very High Limit).

The return string can be converted into clearer form of information about the status of object value - the function [GetValueStatusStr](#), or about the value limit - the function [GetValueLimitStr](#).



Related pages:

[Requirement for status of object value](#)