

PA_NoAlarm	.
PA_ToOn	- ON (TRUE).
PA_ToOff	- OFF (FALSE).
PA_On	- ON (TRUE).
PA_Off	- OFF (FALSE).
PA_Err	().
PA_Oscillate	.
PA_HL	- HL.
PA_VHL	- VHL.
PA_LL	- LL.
PA_VLL	- VLL.
PA_ToHL	- HL.
PA_ToVHL	- VHL.
PA_ToLL	- LL.
PA_ToVLL	- VLL.
PA_SwToTrans	- Q_Trans.
PA_SwToOff	- Q_Off (FALSE).
PA_SwToOn	- Q_On (TRUE).
PA_SwToError	- Q_Err.
PA_SwTrans	- Q_Trans.
PA_SwOff	- Q_Off.
PA_SwOn	- Q_On.
PA_SwErr	- Q_Err.
PA_ErrWriteCmd	.
PA_Change	-

- Switch

PA_ErrCmdOn	cm_SetSwitchOn (ZAP).
PA_ErrCmdOff	cm_SetSwitchOff (VYP).
PA_ErrZalCmdOff	cm_SetSwitchBkpOff (ZÁL. VYP)